

**Daniel  
Wall/SUPR/R7/USEPA/US**  
09/01/2005 12:39 PM

To wren39  
cc Debbie Kring, Cheryle Micinski  
bcc  
Subject Re: Westlake Landfill

Hello:

I am the project manager for EPA on the West Lake Landfill Superfund site. This site is comprised of the old inactive landfilled areas on a 200-acre parcel. Our investigations have shown minimal impacts to on-site groundwater from the inactive landfill areas. Although all of the groundwater wells related to this investigation are in the immediate vicinity of the site, there is unlikely to be significant groundwater impacts off-site from the inactive landfill areas. The Bridgeton Landfill, located on the same property, is an active municipal solid waste landfill operating under a permit with the state. Although not a part of our investigation, I am aware that the landfill actively pumps shallow groundwater/leachate creating a groundwater capture zone through much of the West Lake Landfill property. Outside the influence of these pumping wells, the potentiometric surfaces are very flat but groundwater flow is generally to the north. So, locations to the south of the south of the site are considered upgradient. The largest impact to groundwater from activities on 200-acre parcel are probably due to the former leaking underground storage tank near the asphalt plant in the middle of the property. I believe the tank has been removed but there is still diesel product in the water there.

If you have any questions or just want to discuss this further, give me call.

Thanks,

Dan Wall  
913-551-7710  
Karen Wren <wren39@atcassociates.com>

**Karen Wren**  
<wren39@atcassociates.com  
>

08/29/2005 03:18 PM

Please respond to  
wren39@atcassociates.com

To Daniel Wall/SUPR/R7/USEPA/US@EPA  
cc  
Subject Westlake Landfill

Hello. I am currently doing some work for a customer that owns a property on Boenker Lane, approximately 1/3 mile southeast of this landfill. I am in Michigan and therefore not able to review regulatory files for the landfill. I would like to know if there has been any documented offsite contamination from this landfill that has traveled to the south/southeast toward Boenker Lane. Could you help me with this? Are there any monitoring wells off of the landfill to the southeast?

Karen Wren  
ATC Associates  
TSP Account Manager  
248.669.5140 (W)  
888.270.1639 (TSP Fax)  
248.669.5147 (Novi Fax)

